



Runways

17/35: 5000 x 75 (ASPH-G)

Coordinates

Latitude 42-50-37.748N
Longitude 075-33-41.047W

Communications

CTAF/U 123.0
APP/DEP 126.125 (SYRACUSE)
PCL 122.7

Navigation

Elevation 1134
NM from City 1 NE
Instr Approach NON-PRECISION

Owner/Manager

Owner
Manager MR FREDERICK N KEIB
6610 AIRPORT ROAD

Services

Fuel JETA 100LL
Airframe Repairs MAJOR
Engine MAJOR

Attended MAY-SEP/ALL/0800-2000,OCT
Airline Airport NO
Transportation TAXI, RENTAL CAR, COURTE
Food OFF - 0.5 MILES
Lodging OFF - 1 MILE

HAMILTON NY 13346
Phone (315) 824-6681
Fax (315) 824-6005
E-mail KASfbo@aol.com
Web site

FBO (Location)

KEIB AIR SERVICE INC (E)
(315) 824-6681 Freq 123.0
<http://members.aol.com/KASfbo/>

Remarks

NOISE ABATEMENT PROCEDURES IN
EFFECT - ALL AIRCRAFT MAINTAIN RUNWAY
HEADING UNTIL 2100 FT BEFORE TURNING.
ULTRALIGHTS AND GLIDERS IN AND
AROUND AIRPORT.